

Parts & Accessories Bulletin

November 12, 1987



PAB #365

PART NUMBER 26345-39

OIL PUMP DRIVE GEAR, 25 T

Due to a substantial cost increase, we will no longer offer the above.

However, this drive gear can be replaced with part number 26345-73, if the corresponding gear, part number 26349-54, which is obsolete, is also replaced with part number 26349-73A.

Thank you.



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE