

Parts & Accessories Bulletin

July 21, 1988



PAB #387

XL 883 HORN KIT P/N 69014-88 INSTRUCTION SHEET CORRECTION


The instruction sheet supplied with this kit is incorrect.

The correct routing of the ground wire (step #4) is from the horn mounting bracket to the back side of the chrome horn cover. Please refer to the photo for correct installation.

Horn kits packaged after 7/15/88 will have corrected instruction sheets.

Please route this bulletin to your parts and service department personnel.

Thank you.



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE