

Parts & Accessories Bulletin

September 17, 1990



PAB #466

SIDECAR CONNECTION KIT P/N 87106-79

Sidecar Connection Kit for 1979-1984 FLH Models, will be obsolete when the existing inventory is gone. The individual parts from the kit may be ordered separately and are listed below for your convenience.

<u>Part Number</u>	<u>Description</u>	<u>Qty</u>
559	Cotter Pin	1
6655	Washer	1
6718	Washer	1
7038	Lockwasher	8
7043	Lockwasher	1
7734W	Nut, Slotted	1
7800W	Nut	8
8034	Nut	2
8059	Nut	1
42309-84	Tee	1
42311-58	Plug	1
49064-36	U-Bolt	4
87105-79	Rear Mount	1
87127-36	Connecting Brace	1
87128-36	Connecting Brace	1
87135-36	Bolt	1
87136-36	Washer	1
87138-36	Spring	1
87176-37	Socket Connector	1
87181-37	Washer	1
87205-58	Bracket	1

/466



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE