

Eagle Iron Parts & Accessories Bulletin

April 3, 1992



PAB 492

P.O. Box 1306 Milwaukee, Wisconsin 53201

40031-85T RK O-RING CHAIN CONNECTING LINK KIT

Due to a supplier error, P/N 40031-85T may have been incorrectly packaged with "rivet" type connecting links instead of "clip" type connecting links. These parts would have a package date of 9-91 and would have been shipped between September 1991 and early March 1992.

If you received any of the "rivet" type connecting link kits and would like to return them, please use an "E-Form," write "F" under reason code and state "received rivet type connecting links in lieu of clip type." Prior authorization of the E-Form is not necessary. Your parts account will be credited in full for the amount returned, regardless of broken package quantities.

Please note that it will be necessary to reorder any connecting links you wish replaced, an order will not be entered automatically.

We apologize for any inconvenience this may cause you or your customers.



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE