

Parts & Accessories Bulletin

May 26, 1992



PAB# 493

Genuine O.E. Service Parts Price Increase

As always, we at Harley-Davidson® seek to supply you with the highest "Quality" service parts at the lowest reasonable pricing. Unfortunately, due to increased vendor and manufacturing costs, we have found it necessary to raise pricing on the following parts.

Part No.	Description	New Net	New Sugg. Retail
2522	Stud, Full Thread	\$0.32	\$0.65
2802W	Screw	\$0.27	\$0.55
3507	Screw	\$1.12	\$2.25
6335	Washer	\$0.08	\$0.16
9062	Bearing	\$3.67	\$7.35
14011-82	Fairing Decal	\$3.47	\$6.95
18204-83	Inner Spring	\$3.47	\$6.95
24023-36	Shaft Nut	\$3.35	\$6.70
25414-70A	Derby Cover, Polished	\$13.37	\$22.95
33429-39	Deflector	\$2.47	\$4.95
37550-41B	Clutch Hub	\$96.50	\$193.00
40910-84A	Wheel Spacer	\$4.50	\$9.00
40924-86	Washer, Spring Retainer	\$1.80	\$3.60
41196-73	Spacer	\$2.97	\$5.95
45778-77	Fork Filler Plug	\$3.67	\$7.35
47374-83A	Seat, Mounting Bracket	\$3.97	\$7.95
59159-80	Decal, Front Fender	\$4.60	\$9.20
60642-84	Inspection Cover	\$22.47	\$44.95
87024-85	Steering Damper	\$42.97	\$85.95

Please update your Spring Price Books accordingly. We appologize for any inconvenience this may have caused you.



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE