

Parts & Accessories Bulletin

September 30, 1993



PAB #507

FILLISTER HEAD MACHINE SCREW Part Number 2695W

Harley-Davidson has learned that some H-D dealers have received **FILLISTER HEAD MACHINE SCREWS**, Part No. **2695W**, which **have the incorrect thread pitch** (number of threads per inch). Instead of receiving the correct 2695W screws (size 10 - 24 x 1-1/8 in.) with coarse thread pitch (24 threads per inch), some dealers have received screws (size 10 - 32 x 1-1/8 in.) with fine thread pitch (32 threads per inch). If used in the applications intended for P/N 2695W, these incorrect screws will "cross-thread" or bind in the threaded holes; thread damage to the screws and/or mating parts may occur.

Harley-Davidson is requesting that all dealers check their inventory of SCREW, P/N 2695W. As of the present, we are aware of only one **packaging date--8/93--**in which the incorrect screw was packaged under part number 2695W.

You may return all stock of the incorrect fine-pitch screws 2695W for full credit using the following procedure:

1. Complete a standard Warranty Claim Form referencing this Parts & Accessories Bulletin (PAB #507). Include the completed form in the package of the screws being returned.
2. Attach a return address P-label (Form No. 1248), to the outside of the package.
3. Return the package to Harley-Davidson, Inc. to receive full credit for both the parts and the return postage.

We apologize for any inconvenience this may have caused.



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE