

Parts & Accessories Bulletin

September 2, 1994



PAB #529

1994 Genuine Accessories Catalog Correction

We have recently been made aware of a Part Number misprint in the 1994 Genuine Accessories Catalog and we wanted to relay this information to you. Please ensure this information is routed to employees in your dealership, particularly your **Service and Parts Departments**. It is imperative that this information is communicated and captured because engine damage could occur if the wrong Screamin' Eagle spark plugs are installed.

Part Number Correction:

Page 112, Item A, Screamin' Eagle Spark Plugs, P/N 32321-91 is the incorrect P/N for 1972-1985 XL 1000 Sportsters. The correct P/N for that application is 32322-91. The H-D code XL10S for that particular product is correct.



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE