

Parts & Accessories Bulletin

NOVEMBER 15, 1995



P&A #550

OIL FILTER FITMENT ON EFI VEHICLES

IT CAME TO OUR ATTENTION THAT THE FOLLOWING 2 EAGLE IRON OIL FILTERS WILL NOT WILL NOT WORK ON EFI VEHICLES DUE TO THEIR OVERALL LENGTH.

63805-80T BLACK- MADE IN TAIWAN
63796-77T CHROME-

THE FOLLOWING OIL FILTERS ARE SHORTER AND WILL WORK ON EFI VEHICLES.

63805-80T- BLACK- MADE IN MEXICO
63796-77T- CHROME-

63805-80A- BLACK- OEM
63796-77A- CHROME-

THE EAGLE IRON OIL FILTERS THAT ARE MADE IN TAIWAN ARE TOO LONG AND WILL MAKE CONTACT WITH THE CRANKSHAFT POSITION SENSOR CAUSING POSSIBLE PROBLEMS OR DAMAGE TO THE SENSOR.

REMEMBER WHEN YOU ARE CHANGING THE OIL FILTERS ON ALL VEHICLES ALWAYS CHECK THE OIL FILTER ADAPTER TO ENSURE THAT IT IS TIGHT.

SHOULD YOU FIND A LOOSE ADAPTER REMOVE IT AND CLEAN IT UP. THEN COAT THE THREADS WITH LOCTITE 271 AND INSTALL TO A HEIGHT OF 0.450-0.520. {SEE TECH TIPS #42}



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE