

**GENUINE MOTOR PARTS AND
MOTOR ACCESSORIES BULLETIN**

P&A NO. 1045

DATE: 4/2/2015

**62543-11 Low Profile Fuel Cap Issue**

Harley-Davidson has discovered the low profile fuel cap 62543-11 has a ratcheting issue that causes the cap to be tightened too far down on the tank and can cause it to either lock to the tank or scratch the tank. Please follow the process below to dispose of your defective stock.

Required Dealer Action:

1. Scrap the 62543-11 Fuel Cap kits you have in stock if the package date is prior to 02/24/2015.
2. Re-order more if needed.
3. Please submit a warranty claim per the table below for all kits in dealer stock or kits that have been retailed to a customer but are not registered to the SWR.
4. For claims pertaining to parts already installed on a motorcycle see service bulletin M-1400.

ITEM	DATA
Claim Type	DFS
Problem Part No.	62543-11
Quantity	Could vary
Customer Concern Code	9203
Condition Code	1518
Note: Enter PAB 1045 in Event Comments	
Additional Note: Do not use a VIN when submitting these claims.	

Questions

Please contact Technical Service with any concerns regarding application. Please direct all other questions to your Dealer Services Representative.

