

SERVICE BULLETIN INDEX

This is the index of all Motorcycle Service Bulletins which may be of current interest to dealers. The index does not include bulletins which are no longer applicable such as former warranty policies and literature lists. Safety Recall Bulletins will be covered in a later Service Bulletin but are included in this index for your convenience.

This index covers Bulletin numbers 500 through M-800 which are listed in numerical order by the following groups: FL/FX Models, FLT Models, XL Models, Lightweight Models, Other Models and Miscellaneous Topics. Bulletins of a general nature such as tools, oil recommendations, etc., are listed under Miscellaneous Topics.

If a Bulletin refers to more than one model group such as XL and FX models, it is listed in each group. Bulletins which have been updated are listed only by the latest Bulletin number such as 782A or 618C.

Bulletins usually, but not always, refer to models that were current at the time of issue. Therefore, if you are working on a 1975 FX motorcycle, you would look in the index under FL/FX Models for Bulletins issued in September 1974 or later.

We recommend you keep this index with your Service Bulletin file for easy reference. This index or parts of it will be updated in the future.

HARLEY-DAVIDSON MOTOR CO., INC.

MISCELLANEOUS TOPICS

SERVICE BULLETIN NUMBER	ISSUE DATE	ITEM COVERED
500	11/20/64	Electric Starter Warning
501	12/11/64	New Shop Service Tools
502	12/11/64	Starter Tests — With Sun Vat-26
503	12/31/64	Generator Brushes — 12v. & 6v.
507	2/18/65	Brake & Clutch Lever Changes
513	5/18/65	Seat Cover — Buddy Seat
516B	10/15/66	Chassis Service and Handling
540A	6/6/80	Speedometer/Tachometer Warranty Service
546A	1/8/69	Gas Line Hose Changes
561	10/16/67	Oil Recommendations
588A	10/9/69	Front Brake Light Switches
596	9/16/69	New Numbering System — VIN
608	4/9/70	Loose Fuel Valve Handles
615	9/28/70	New Service Tools
616	9/30/70	Tire Balance/Wheel Weights
623	4/15/71	Spark Plug Heli-Coil Kit
625	8/2/71	Low Lead Gasoline
689	5/5/75	Service Tools — Lightweights
M-712	6/16/77	Hydraulic Brake System Maintenance
M-725	2/14/78	EPA Changes
M-800	10/10/80	17 Digit VIN System

ROUTING:	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	CHIEF MECHANIC	MECHANIC NO. 1	MECHANIC NO. 2	MECHANIC NO. 3	MECHANIC NO. 4	RETURN THIS TO:
INITIAL HERE									

FL/FX MODELS

SERVICE BULLETIN NUMBER	ISSUE DATE	ITEM COVERED
508	3/19/65	Siren Conversion
509	3/19/65	Transmission Oil Seal
512	5/18/65	Upper Shock Stud Change
519	10/5/65	Primary Drive Chain Care
521	10/11/65	Generator Brush Location
523	10/18/65	Cylinder Base Nuts
524	10/29/65	Lubrication System
527	12/1/65	Two-piece Oil Ring
532	1/17/66	Circuit Breaker Protection
534	2/17/66	Drive Chain — Press Fit Link
536	3/7/66	New Starter
538B	9/25/69	Chain Housing Vent Kit
542	7/15/66	New Gas Line Filter
543	8/8/66	Starter Change — Drain Holes
547	10/24/66	Tillotson Carburetor Inlet Valve
549	2/8/67	Police Solo Recommendations
551	2/20/67	Starter Relay Conversion Kit
552	2/21/67	Motor Sprocket Spacer
556	7/21/67	Rear Brake Hose Guide (Recall 002) — 1967 FL
562A	5/11/69	Set Timing in Advance Position
564	1/15/68	Tillotson Carburetor Serviceability
567	3/25/68	Clutch Lever Pin and Bushing Changes
569	4/12/68	Oil Filter Kit
571	5/21/68	Tillotson Accelerator Pump Change
572	6/10/68	Control Cable Anchor Pin
573	7/11/68	Clutch Throwout Bearing
574	7/12/68	Exhaust Pipe Gasket P/N 64834-68
576	8/25/68	Cylinder Base Nuts
577	9/13/68	5.10 x 16 Replaces 5.00 x 16 Tire
581	12/15/68	Oil Pump Nut & Bolt Tightness
583	12/15/68	Siren Pivot Shafts
587	2/28/69	Oil in Clutches
589	7/3/69	Rear Brake Pedal Lever (Recall 006) — 1967-68 FL
591	6/23/69	Sprocket Shaft Bearing Endplay
592	6/17/69	Oil Filter Vent Hole
593	6/17/69	Rocker Arm Cover Gasket
599	11/7/69	Cam Seal Relief Hole
600	11/7/69	Alternator System Checks
605	11/28/69	Idle Mixture Screw
609	5/11/70	Wheel Bearing Locknut (Recall 008) — 1969-70 FL
611	5/20/70	Carburetor Jet
614A	4/14/71	Carburetor/Timing Marks/Compensating Sprocket
619	1/25/71	Rear Brake Rod Clevis (Recall 009) — 1971 FX
620	3/25/71	License Plate Support Bracket — FX Models
627	10/11/71	Point Cam and Lubrication
630	11/8/71	Rear Brake Hydraulic Line (Recall 013) — 1971-72 FL/FX
633	2/15/72	Front Disc Brake Information — FL Models
635	2/18/72	Sprocket Shaft Bearing Oil Hole
638	8/14/72	Front Wheel Hub Lockring (Recall 017) — 1972 FX
643	12/18/72	Disc Brakes (Recall 018) — 1973 FL/FLH/FX
647	4/10/73	Oil Pumps
651	6/27/73	Front Fork Lower Bracket (Recall 021) — 1973 FX
653	7/30/73	Disc Brake Caliper Mounting Pin Kit
658	1/7/74	Battery Support Bracket — FL Models
659	3/6/74	Fusible Wire
661	4/15/74	Rear Fender Reinforcement — FX Models
662	4/29/74	Rear Brake Caliper (Recall 024) — 1973-74 FL/FLH/FX/FXE
669	8/16/74	Ignition Coils
673	10/9/74	Oil Ring Change

FL/FX MODELS (CONT'D.)

SERVICE BULLETIN NUMBER	ISSUE DATE	ITEM COVERED
675	10/14/74	Ignition Switch — FX Models
676	10/14/74	Jiffy Stand Support Plate — FX Models
677	10/14/74	Foot Shifter Timing — FX Models
680	1/31/75	Spark Plug Change
685	3/20/75	Liberator Fairing Handlebar Mounting Bolts (Recall 026) 1972 & Earlier — FL/FLH
687	4/8/75	Clutch Throwout Bearing Change
694	11/7/75	Keihin Carburetor
695	11/7/75	Wheel Spokes (Recall 029) — 1975 FX/FXE
697	3/29/76	Bendix Carburetor — Jet Identification
701	5/26/76	Rear Disc Brake Service Information
705	11/11/76	Ignition Advance Unit Lubrication
706	10/15/76	Rear Disc Brake (Recall 031) — 1974-76 FL/FLH/FX/FXE
M-707	12/1/76	Keihen Carburetor/Adjustment/Modification
709	3/22/77	Front Brake Caliper Mounting Bolts (Recall 032) — 1975-77 FX/FXE
710	5/6/77	Clutch Push Rod Thrust Washers
M-713	6/10/77	Keihen Carburetor
M-714	8/16/77	Piston Pin Retaining Ring Changes
M-715	8/12/77	Air Cleaner Gasket and Heat Spacer
M-717	9/13/77	Front Fork Change — FL Models
M-718	9/13/77	Transmission & Cam/Pinion Changes
M-721	10/21/77	Rear Brake Master Cylinder O-Ring (Recall 034) — 1978 FX/FXE/FXS
M-724	2/7/78	Electronic Ignition Timer Wires
M-726	3/30/78	Front Brake Caliper Bolt Washer (Recall 035) — 1978 FX/FXE/FXS
M-729	6/13/78	Carburetor Low Speed Setting — FLH-80
M-730	6/15/78	High Altitude Carburetor Kit
M-731	6/20/78	Tire Fitment
M-732	6/27/78	Hydraulic Lifters
M-734	7/5/78	Wheel Bearing Spacers
M-735	7/14/78	Flywheel Assembly
M-736	7/31/78	Front Brake (Recall 037) — 1978-79 FL/FX Models
M-737	8/3/78	Disc Brake Changes
M-738	10/17/78	Lacing 16" Wheels (New Hub)
M-739	11/3/78	Carburetion and Ignition
M-740	11/30/78	Primary Chain Tensioner (black)
M-741	1/12/79	Front Brake Caliper (Recall 038) — 1979 FLH/FLH-80
M-742	1/31/79	Classic King Tour Pak — FL Models
M-743	4/3/79	Cam Gear Selection
M-745	4/24/79	Improving Oil Mileage
M-746	5/11/79	Push Rod Covers (loss of vacuum)
M-747	5/1/79	Front Brake Master Cylinder (Recall 039) — 1979 FL/FX Models
M-748	5/18/79	Miscellaneous Information — 1979 Models
M-750	6/15/79	Tappet Guide Blocks
M-752	7/6/79	Frame Mounted Seat (Recall 042) — 1979 FLH/FLH-80
M-753	8/14/79	Rear Brake Master Cylinder Change
M-754A	3/21/80	Rear Brake Master Cylinder Piston (Recall 044) — 1979 FL/FX Models
M-756	10/16/79	Frame Mounted Seat Reinforcement Kit — FL Models
M-758	10/23/79	Rear Brake Master Cylinder Piston (Recall 044) — 1979 FL/FX Models
M-760	11/16/79	Resistor Plugs and Ignition Rotor Bolt
M-761	11/30/79	Piston Replacement — Early 1980
M-762A	4/1/80	Front Chain Housing
M-763	12/21/79	Starter Relay — 1974 to 1979
M-763A	3/21/80	Front Fender Mounting (Recall 045) — 1975-80 FL Models

FL/FX MODELS (CONT'D.)

SERVICE BULLETIN NUMBER	ISSUE DATE	ITEM COVERED
M-799	10/17/80	Service Information — 1981 Models
M-766	2/29/80	Brake Fluid/Sidecar
M-767	3/4/80	Square Seal Brake Caliper
M-769	4/18/80	Service Information — 1980 Models
M-771	5/9/80	Oil Pump Gasket & Cover Changes
M-772	4/22/80	1340cc Low Compression Pistons
M-774	4/25/80	Gear Shaft — 1958 to 1972
M-775	5/6/80	Belt Adjustment and Alignment Procedure — FXB
M-780	5/23/80	Revised Ignition Timing
M-781	5/23/80	Ignition Timing Marks
M-782A	6/20/80	Three Angle Valve Seats
M-785	6/10/80	Rear Brake Master Cylinder Piston (Recall 044) 1979 FL/FX Models
M-786	8/29/80	Interchangeable Front Brake Piston — 1972 to Early 1980
M-788	6/3/80	Cylinder Heads, Intake Manifold & Clamps
M-789	6/6/80	Cast Iron Valve Guides — Pre-1980
M-790	6/10/80	Service Information — 1980 Models
M-791	7/25/80	Cylinder Head Temperature Gauge Kit — P/N 75000-69A
M-793	7/3/80	Ignition Coils — 1980 Models
M-794	7/14/80	Rear Brake Control Mounting Bolts (Recall 050) — 1980 FXWG
M-798	10/7/80	Rear Brake Caliper Maintenance — FLH Models
M-799	10/17/80	Service Information — 1981 Models

FLT MODELS

SERVICE BULLETIN NUMBER	ISSUE DATE	ITEM COVERED
M-765	3/14/80	Rear Brake Caliper (Recall 046) — 1980 FLT
NONE	3/7/80	Sprocket Mounting Screws (Recall 047) — 1980 FLT
M-769	4/18/80	Service Information — 1980
M-770	3/31/80	Ignition Switch/Fork Lock Assembly (Recall 048) — 1980 FLT
M-771	5/9/80	Oil Pump Gasket & Cover Changes
M-772	4/22/80	Low Compression Pistons
M-780	5/23/80	Revised Ignition Timing
M-781	5/23/80	Ignition Timing Marks
M-782A	6/20/80	Three Angle Valve Seats
M-783	5/23/80	Accessory Gauge Kit Installation
M-784	5/23/80	Service Procedure
M-787	6/3/80	Fork Lock Adjusting Screw (Recall 049) — 1980 FLT
M-788	6/3/80	Cylinder Heads, Intake Manifold & Clamps
M-790	6/10/80	Service Information — 1980
M-792	7/3/80	Electrical Charging System Diagnostic Procedure
M-793	7/3/80	Ignition Coils
M-795	7/22/80	Sprocket Mounting Bolts (Recall 051) — 1980 FLT
M-796	9/16/80	Front Fork Lock
M-797	10/10/80	Service Information — 1980 & 1981
M-798	10/7/80	Rear Brake Caliper Maintenance — 1980 & 1981

XL MODELS

SERVICE BULLETIN NUMBER	ISSUE DATE	ITEM COVERED
515	6/11/65	Change to No. 4 Spark Plug
518	9/10/65	Change to Tillotson Carburetor
521	10/11/65	Generator Brush Location
523	10/18/65	Cylinder Base Nuts
527	12/1/65	Two-piece Oil Ring
534	2/17/66	Drive Chain — Press Fit Link
537	3/22/66	Crankcase Filter and Countershaft Low Gear
541	7/15/66	Transmission Shifter Cam Assembly
545A	6/7/68	Rear Wheel Tube Flap — P/N 43148-67
547	10/24/66	Tillotson Carburetor Inlet Valve
553	2/24/67	Spark Plug Cable Guide (Recall 001) — 1967 XLCH
562A	5/11/69	Set Timing in Advance Position
563	11/29/67	Hydraulic Fork Oil Capacity
564	1/15/68	Tillotson Carburetor Serviceability
569	4/12/68	Oil Filter Kit
571	5/21/68	Tillotson Carburetor Accelerator Pump Changes
572	6/10/68	Control Cable Anchor Pin
582	12/17/68	Sprocket Changes — 20-19 Teeth
591	6/23/69	Sprocket Shaft Bearing Endplay
592	6/17/69	Oil Filter Vent Hole
593	6/17/69	Rocker Arm Cover Gasket
597	9/16/69	Tapered Bead Tires/Rims
598	9/29/69	Fiberglass Seats
605	11/28/69	Idle Mixture Screw
606	11/28/69	Rear Brake Light Switch Kit — P/N 72004-67
618C	12/17/74	Kicker Gear Kits
622	6/9/71	Clutch Improvements
624	4/30/71	Rear Wheel Hub (Recall 012) — 1971 XLH/XLCH
627	10/11/71	Point Cam and Lubrication
634	2/18/72	Clutch Adjustment
636	4/27/72	Rear Fork Bearing (Recall 015) — 1972 XLH/XLCH
638	8/14/72	Front Wheel Hub Lockring (Recall 017) — 1972 XLH/XLCH
650	5/15/73	Tail Lamp Wiring (Recall 020) — 1973 XL/XLCH
651	6/27/73	Front Fork Lower Bracket (Recall 021) — 1973 XL/XLCH
652	7/30/73	Head and Cylinder Changes
653	7/30/73	Disc Brake Caliper Mounting Pin Kit
654	8/27/73	Rear Brake Lever (Recall 022) — 1973 XL/XLCH
655	11/15/73	Directional Arrow — Rear Tire
656	2/11/74	Frame Reinforcement/Tail Lamp Wiring (Recall 023) — 1973 XL/XLCH
659	3/6/74	Fusible Wire
661	4/15/74	Rear Fender Reinforcement
663	4/29/74	Clutch Changes
669	8/16/74	Ignition Coils
675	10/14/74	Ignition Switch
678	12/17/74	Rocker Arm Covers "M"
686	4/8/75	Transmissions
688	5/12/75	Rear Fork Bearing Kit — P/N 47550-74
695	11/7/75	Wheel Spokes (Recall 029) — 1975 XL/XLCH
697	3/29/76	Bendix Carburetor Jets
702	5/28/76	Rear Brake Shoes (Recall 030) — 1976 XL/XLCH
705	11/11/76	Ignition Advance Unit Lubrication
709	3/22/77	Front Brake Caliper Mounting Bolts (Recall 032) — 1975-77 XL/XLCH/XLT
M-708	12/1/76	Breather Valve
M-711	6/3/77	Oil Pump Cover
M-713	6/10/77	Keihin Carburetor
M-714	8/16/77	Piston Pin Retaining Ring Changes

XL MODELS (CONT'D.)

SERVICE BULLETIN NUMBER	ISSUE DATE	ITEM COVERED
M-716	8/26/77	Showa Rear Shock Absorber (Recall 033) — 1977 XL-1000
M-719	9/13/77	Rear Fender
M-727	4/11/78	Rear Brake Control Linkage (Recall 036) — 1979 XLH-1000
M-730	6/15/78	High Altitude Carburetor Kit
M-731	6/20/78	Tire Fitment
M-734	7/5/78	Wheel Bearing Spacers
M-735	7/14/78	Flywheel Assembly
M-736	7/31/78	Front Brake (Recall 037) — 1978-79 XLH/XLCH
M-737	8/3/78	Disc Brake Changes
M-738	10/17/78	Lacing 16" Wheels (New Hub)
M-739	11/3/78	Carburetion and Ignition
M-743	4/3/79	Cam Gear Selection
M-744	4/3/79	Transmission Changes
M-747	5/1/79	Front Brake Master Cylinder (Recall 039) — 1979 Models
M-749	6/12/79	Rear Brake Master Cylinder Pushrod (Recall 040) — 1977-78 XLCR-1000
M-751	6/29/79	Rear Brake Pedal Stop Bolt Jamnut (Recall 041) — 1979 XLH/XLS
M-754A	3/21/80	Rear Brake Master Cylinder Piston (Recall 044) — 1979 XLH/XLCH/XLS
M-755	9/7/79	Rear Brake Pedal (Recall 043) — 1978-79 XLH/XLCH/XLS
M-757	10/19/79	Cam Timing
M-758	10/23/79	Rear Brake Pedal (Recall 043) / Rear Brake Master Cylinder (Recall 044) — 1978-79 Models
M-759	10/16/79	Battery Position
M-760	11/16/79	Resistor Plugs and Ignition Rotor Bolt
M-763	12/21/79	Starter Relay — 1974 to 1979
764	12/21/79	Shock Absorber Bushing
M-768	3/18/80	Crank Pin/Chain Adjuster
M-769	4/18/80	Service Information — 1980
M-773	4/25/80	Shock Absorbers
M-776	5/9/80	Solenoid Cover — 1977 to 1980
M-777	5/13/80	Cylinder Head Gaskets
M-778	5/13/80	Crankcase Cover Gasket
M-779	5/23/80	Rear Brake Clevis Rod End
M-780	5/23/80	Revised Ignition Timing
M-781	5/23/80	Ignition Timing Marks
M-785	6/10/80	Rear Brake Master Cylinder Piston (Recall 044) — 1979 Models
M-793	7/3/80	Ignition Coils

LIGHTWEIGHT MODELS

SERVICE BULLETIN NUMBER	ISSUE DATE	ITEM COVERED	MODELS COVERED
506	2/18/65	Spoke Information	M-50
511	5/14/65	Transmission Gears	M-50
514	6/11/65	New Wheel Bearings	M-50
517	7/7/65	Remove Engine Oil	M-Models
525	11/16/65	2-Cycle Oil for Transmission	M-50/M-50S
526	12/1/65	Carburetor Throttle Stop Eliminated	Sprint
535	2/17/66	Spoke Tightness	Sprint
539A	11/29/67	Factory Repair	M Models
544A	12/1/66	Pre-Delivery and Service	1967 Sprint
554	4/28/67	Optional Gearing and Ignition Timing	1967 Sprint
555	6/19/67	Exhaust Port Seal	M-125
559	10/13/67	Circuit Breaker Timing	Sprint
560	10/13/67	500 Mile Service	Sprint
563	11/29/67	Hydraulic Fork Oil Capacity	M-125
565A	3/1/68	Stoplight Switch (Recall 003)	1968 M-125 Rapido
566	1/25/68	Throttle Control Grip Retaining Screw (Recall 004)	1968 M-125 Rapido
568	4/5/68	Air Filter Stud	Sprint
578	9/25/68	Tail Lamp Wiring (Recall 005)	1969 MLS Rapido
579A	1/8/69	Gas Tank Valve	Sprint/Rapido
580	10/18/68	Engine Numbering System Changed	1969 Lightweights
584	1/10/69	Tune-Up Information	1969 Sprint
585	2/14/69	New Fuse Holder	Sprint SS
586	2/14/69	Exhaust Valve Clearance	Sprint
590A	8/24/70	Generator Armature & Shaft Taper	Sprint
594	7/15/69	New Spark Plug	M-Models
595	9/16/69	Flywheel Endplay — Spring Washer	Sprint
601	2/6/70	Starter Gears	1969-70 Sprint
603	11/26/69	1970 MLS Electrical System	1970 MLS/M65S
604	4/9/70	Fork Vent Valve	1970 Sprint
607	2/6/70	Rear Brake Switch	1969-70 Sprint
610	5/20/70	Front Fork Oil Seals	Baja
612	6/16/70	Throttle Cable	All Lightweights
613	8/24/70	Rings/Piston Change	Baja
621	6/9/71	Design Changes	1971 Sprint
626	8/2/71	Charging System	1971 Sprint
628	10/19/71	Front Wheel and Axle (Recall 014)	1972 Shortster
629	11/9/71	Magneto/Generator	1971 Rapido
637	7/7/72	Front Fork Slider (Recall 016)	1972 MC-65 Shortster
639	9/25/72	Silver Gas Tank Trim	All Lightweights
640	4/25/73	Front Axle Assembly	1973 Z-90
641	11/15/72	Rear Brake Sideplate	1973 Z-90
642	12/13/72	Tune-Up Information	1973 Sprint
644	3/26/73	Injection Oil Pump	1973 XZ-90, TX-125
645 & 646	4/5/73	High Output Alternator	1973 Sprint
648	4/25/73	Front Brake Sideplate Retainer (Recall 019)	1973 Z-90
649	5/25/73	Front Axle Locknut Kit	Z-90
657	12/17/73	Oil/Spark Plug	1974 SX-175
660	3/4/74	Spec's./ Clutch/Rear Wheel	1974 SX-175
664	4/29/74	Fuse	1974 SX-175

LIGHTWEIGHT MODELS (CONT'D.)

SERVICE BULLETIN NUMBER	ISSUE DATE	ITEM COVERED	MODELS COVERED
665	6/10/74	Front Brake Sideplate — P/N 44143-73	1973 Z-90
666	7/10/74	Ignition System	1974 SX-175
667	6/21/74	Air Cleaner Care	1974 SX-175
668	8/26/74	Front Wheel Tire Bead Clamp/ Rear Brake Sideplate (Recall 025)	1974 SX-175
670	10/7/74	Exhaust System Cleaning	SX-175
671	10/7/74	Rear Wheel Spokes	SX-175
672	10/9/74	Carburetor Modification	SX-175
674	10/14/74	Air Cleaner & Carburetor	1974 X-90/Z-90
679	12/17/74	High Voltage Problem	X-90
681	1/31/75	Electric Starter Motor	1973-74 Sprint
682	1/31/75	Spoke Maintenance	Sprint
683	1/31/75	Throttle Grip Fix — P/N 44186-74P	X/Z-90, SX/TX-125
684	2/13/75	Reinforced Crankcase Cover	SX-175/250
690	5/12/75	Air Filter Cover	1975 SXT-125
691	5/12/75	Jiffy Stand Bracket	SS-250
692	6/27/75	Rear Brake Pedal Lever (Recall 027)	1975 SS-250
693	9/9/75	Frame (Recall 028)	1975 SXT-125
694	7/23/75	Ignition Switches	All Lightweights
696	11/7/75	High Idle	SS-250
698	3/29/76	Rear Brake Switch Kit — P/N 72200-75	All Lightweights
699	8/16/76	Carburetor Modification	1975 SX-250/SS-175
700A	8/16/76	Service Information	MX-250
703A	9/3/76	Oil Supply Fitting	SS/SXT-125
704	8/16/76	Spark Plug	1975-76 SS/SXT-125
M-720	10/11/77	Front Fender Installation	MX-250
M-722	11/4/77	Auto Retard Alternator	1976 SS/SX-175/250
M-723	1/13/78	Flasher	1978 Lightweights
M-728	4/28/78	Flywheel Assembly	1978 MX-250
M-733	7/7/78	Gas Caps/Mounting Screws/Rear Chain	1978 Lightweights

OTHER MODELS

SERVICE BULLETIN NUMBER	ISSUE DATE	ITEM COVERED	MODELS COVERED
504	1/18/65	1964-65 Electric Starter Service	Servi-Car
522	9/30/65	Testing Servi-Car Elec. System	Servi-Car
523	10/18/65	Cylinder Base Nuts	Servi-Car
534	2/17/66	Drive Chain — Press Fit Link	Servi-Car
536	3/7/66	New Starter	Servi-Car
562A	5/11/69	Set Timing in Advance Position	Servi-Car
669	8/16/74	Ignition Coils	Servi-Car
M-766	2/29/80	Brake Fluid — Sidecar	LE/CLE