



HEADLIGHT MODULATOR

91706-82

The instruction sheet in the headlight modulator, P/N 91706-82, calls out a yellow, a red, and a green wire from the unit. Actual production units have a red, a white, and a black wire. To correct the instruction sheet, the yellow wire should say black, and the green wire should say white. The red wire is okay.

Please open any stock you have and change the diagram (Figure 1) to show the correct color codes on wiring. NOTE: Improper hook-up can cause immediate failure of unit.

IMPORTANT NOTICE***READ IMMEDIATELY***