Parts & Accessories Bulletin

APRIL 13, 1987



P&A #341

P/N 65213-86 FXST Hi-Performance Exhaust System by Kerker

Read this bulletin carefully. Fitment clarification and a change in the installation procedure are outlined below.

The new 1987 Genuine Accessories Catalog has an error regarding fittment for this FXST exhaust system, part no. 65213-86 on page 8. The correct fitment is as follows:

P/N 65213-86 Fits 1984 to 1987 FXST models.

There are **NO** interference problems with the 1987 1/2 Hayes rear brake master cylinder and this FXST exhaust system.

The installation procedure outlined in the Instruction Sheet supplied with the Kerker exhaust system kit part no. 65213-86 is wrong. The following is a corrected installation procedure.

See Figure 1. Figure 1 shows the original illustration and a corrected version. Item # 4 and item # 11 clamps must be interchanged, as shown in the corrected version, to properly install the exhaust system.

Please file this Bulletin in your copy of the Dealer Accessory Guide for future reference.





