Parts & Accessories Bulletin

JANUARY 12, 1988



PAB #369

BRAKE PAD SET PART NO. 44135-74

The FL and FX Part Catalogs (P/N 99456-84 and 99455-83B, respectively) and the microfiche list the above pad set for 1972 to early 1978 FL and FX models. This pad set contains sintered bronze (metallic) pads that must not be installed on 1972 - 1975 FL/FX models equipped with the original hard chrome plated brake discs. The metallic pads will cause severe scratching of the disc (s). See the following tabulation for information on identifying compatible disc/pad combinations for 1972-1975 FL/FX motorcycles.

BRAKE DISC		PAD INFORMATION
Part No. & Usage	Identification	
41806-72, used on 72-75 FL front and rear & FX rear	Center offset, chrome plated and marked "MIN. THICKNESS .188"	Designed for use with organic pads, Part No. 44131-72. These pads are OBSOLETE.
41806-72B, disc & spacer P/N 41814-76	P/N 41813-76 stamped on disc and marked"MIN. THICKNESS .188"	Designed for use with metallic pads, Part No. 44135-74.
41813-79 & spacer, P/N 41814-76 for rear wheel or P/N 41814- 76A for front wheel (front wheel spacer has notch for speedometer drive on later models)	P/N 41813-79 stamped on disc and marked "MIN. THICKNESS .205"	Compatible for use with metallic pads, Part No. 44135-74.

SUMMARY:

If Pad Set, Part No. 44135-74 is installed on 1972 - 1975 models the original discs must be replaced with Part No. 41806-72B or Part No. 41813-79 discs and appropriate spacer. Spacer must be installed between wheel hub and brake disc.

