

Parts & Accessories Bulletin

September 5, 1989



PAB #431

SPORTSTER® SADDLEBAG

SUPPORT AND SISSY BAR SIDEPLATE KITS

(PART NUMBERS 90799-86 AND 52782-82A)

It has come to our attention that because of fender support design changes on the 1990 Sportster, the above mentioned accessories cannot be installed on 1990 XL models.

The proper fitment for XL Side Plate Kit, P/N 52782-82A, and XL Saddlebag Support Kit, P/N 90799-86, is 1982-1989 XL models.

We apologize for any inconvenience this may have caused and will inform you shortly regarding new part numbers required for 1990 XL models.



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE