

Eagle Iron Parts & Accessories Bulletin

September 18, 1990



PAB 472

P.O. Box 1306 Milwaukee, Wisconsin 53201

Attention: Sample Program Participants

Due to an error in packaging of the August 24, 1990, sample there is a possibility that some dealers may not have received the correct quantity of p/n 99020-90T "Gold Eagle" gas cap medallion. This part should have been in a package quantity of 4 pieces. If you did not receive the correct amount, please submit an E-form for the shortage amount only and Harley-Davidson will ship them free of charge.

We apologize for any inconvenience this may cause.

Thank you.



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE