

Parts & Accessories Bulletin

PAB #483



October 25, 1991

WHEEL BEARING SPACERS

Wheel Bearing spacing for all 1992 models has been changed to a new spacer with shims to set the proper wheel bearing end play. The old bearing spacer system was achieved with a selection of three different color coded spacers chosen for the best bearing end play. Please refer to Service Bulletin M-1013.

The three color coded spacers will not be available after the current inventory of parts has been sold. This will require that all 1991 and earlier systems be updated to the new 1992 spacer system when servicing wheel bearings becomes necessary.

OLD SPACERS	MUST USE BOTH PARTS		AS NECESSARY TO ACHIEVE CORRECT END PLAY				
	NEW SPACERS	SPACER WASHER	.032 SHIM	.016 SHIM	.008 SHIM	.004 SHIM	.002 SHIM
43601-78A 43602-78A 43603-78A	43668-82	43650-82	43290-82	43291-82	43292-82	43293-82	43294-82
43623-78 43624-78 43625-78	43613-92	43650-82	43290-82	43291-82	43292-82	43293-82	43294-82
43630-79 43631-79 43632-79	43634-92	43650-82	43290-82	43291-82	43292-82	43293-82	43294-82
43604-78 43605-78 43606-78	43608-82	43650-82	43290-82	43291-82	43292-82	43293-82	43294-82
43637-89 43638-89 43658-89	43612-92	43650-82	43290-82	43291-82	43292-82	43293-82	43294-82



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE