

Parts & Accessories Bulletin

March 30, 1992



PAB #490

We at Harley-Davidson strive to supply you with non-current "Quality" Service parts. In order to reach that goal, we have to pass along price increases to you in order to still service "our" customers. Due to increased manufacturing costs because of very low demand, it is necessary to increase pricing for the following Genuine O.E. Service Parts.

Part No.	Description/Application	New Net	New Sugg. Retail
<u>'58 - '86 1340 Models</u>			
24645-81	Set Gear Shaft Bearings, .0005 O.S.	\$46.10	\$65.85
24649-81	Set Gear Shaft Bearings, .0003 O.S.	\$49.21	\$70.30
24650-81	Set Gear Shaft Bearings, .0001 O.S.	\$47.32	\$67.60
24651-58	Bearing Set, .0002 O.S.	\$49.04	\$70.05
24652-58	Bearing Set, .0004 O.S.	\$49.69	\$70.99
24653-58	Bearing Set, .0006 O.S.	\$46.52	\$66.45
24654-58	Bearing Set, .0008 O.S.	\$52.33	\$74.75

Please update your price books accordingly. We apologize for any inconvenience this may cause you.



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE