

# Parts & Accessories Bulletin

2/27/95



PAB #539

## **FLHR Saddlebag Guardrails P/N 90839-94** **Return Procedure**

This bulletin is to notify all dealers on the sample program that a very small quantity of the **FLHR Saddlebag Guardrails** that were recently sampled may be **defective** due to chrome plating fluid staining/corroding the chrome finish. (See March P&A News for details) As a result we have set up the following return procedure to ensure you receive a first quality sample set of guardrails without having to re-order another pair.

Ship the stained set of guardrails with a copy of your Dealership Letterhead enclosed in the package. On that letterhead, copy the amount for freight pre-paid by you for the return shipment with your dealer number and signature. We must have this information to credit the freight charge to your P&A account. Return the guardrails to:

**FLHR Saddlebag Guardrail Return**  
**12572 Delta Drive**  
**Taylor, MI 48180**

Upon receipt of the returned guardrails, we will immediately ship a first quality pair freight pre-paid.

This special return/replenishment procedure is intended to fulfill **only sample program** orders that may be defective for **this one product**. All future shipments of guardrails filling existing back orders will be first quality product.



**FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE**