

Parts & Accessories Bulletin

March 7, 1995



#540

CATALOG CORRECTIONS

Genuine Accessories Section

Page 16 Item C & D Part Number 52545-84

This item is listed twice and shown in both photos. The description is Low Pillow Look Backrest Pad.

Page 26 Item C Part Number 40317-94

This item is a 65 Tooth Belt Sprocket Cover. Fits all '95 worldwide Softail models. Also fits '94 International Softail models and Swiss 1340 '94-'95 models.

Page 26 Item F Part Number 91004-94

The correct price is \$470.00

Page 39 Item G Part Number 61655-91

Gas Tank Trim Panel does not fit FXDWG, Dyna Super Glide, and Dyna Convertible

Page 61 Item F Part Number 52738-94

SOFTAIL MINI RAIL was not listed. Fits all '84 and later Softail models with H-D Sissybar Sideplate Kits and Badlander Custom Seat. \$47.95

Page 67 Item E & F

The photos are reversed. Item E is a photo of Rear Fender and Item F is a photo of a Front Fender.

Page 67 Item F Part Number 59596-89

Price is \$119.95

Page 74 Item A

Electra Glo Light Rails - The "Note" at the bottom should read: Note: to install on '93 FLHS and '94-'95 FLHR models, Saddlebag Guard Kit, P/N 90839-93A (see page 84, item A) is required and must be purchased separately. (The remainder of the note is correct.)

Page 74 Item B

The part number for the Candy Sapphire Sun-Glo is 58374-91VN.



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE

Parts & Accessories Bulletin

March 7, 1995



#540

Page 75 **Item G**

Fits only FLHT does not fit FLT.

Page 80 **Item F** **P/N 52548-87B**

Also fits '95 FLHT Standard.

Page 89 **Item E** **P/N 77127-93**

Price should be \$399.95.

Page 89 **Item F**

A pair of saddlebag liners are shown. The Part Number is 91847-88 (pair) and was not listed. *This part is obsolete.* The photo was not adjusted to reflect this.

Eagle Iron Section

Page 142 **Item C**

Should read: P/N 67786-86T Plain

P/N 67735-91T, 67735-88T, and 67734-88T fit 86 -'95 FLHT FLHTC, and FLST (front).

P/N 67738-91T, 67738-88T, and 67737-88T fit '88 - '95 FLHTC (front), and '86 -'95 FLT, FLST, and FXRT(rear).

Page 142 **Item D**

Should read: 68006-83T Plain

P/N 68013-91T, 68013-88T, 68012-88T, 68015-88T, and 68014-88T fit '80 -'95 FXWG, FXST, and FXDWG models.

Page 142 **Item E** **Headlamp Visors**

Fits 7" Headlamp (except FLHR).

P/N 67791-91T Gold Eagle Wing Logo

P/N 67791-87T Eagle Wing Logo

P/N 67752-77T Plain

Fits 5 3/4" Headlamp

P/N 67751-91T Gold Eagle Wing Logo

P/N 67751-88T Eagle Wing Logo

P/N 67750-88T Plain



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE

Parts & Accessories Bulletin

March 7, 1995



#540

Page 142 Item E

Please add : Passing Lamp Trim Ring P/N 6877-93T \$16.95. Replaces original equipment P/N 68725-62. Required for proper installation of Eagle iron visors on '87 and later models.

Page 161 Item G

Chrome Allen Plug Hole Kit 94131-93 should read 94131-93T.

Page 164 Item G (8 & 9)

P/N 56086-81T has no dimple for wiring.

P/N 56081-82T has a dimple for wiring.

Page 183 Item D

P/N 22253-73TA should read 22253-72TA.

Note: For the Dual Fishtail Exhaust, P/N 65281-92B, the Forward Control Kit (P/N 49163-91) cannot be installed and vice versa.



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE